MCAS EL TORO, CALIFORNIA

Installation Restoration Program

Report
Interim Groundwater Treatment System
Monthly Monitoring Reports - AUGUST

1990

JMM James M. Montgomery

Consulting Engineers Inc.



MCAS EL TORO
INTERIM GROUNDWATER TREATMENT SYSTEM
MONTHLY MONITORING REPORT
AUGUST 1990

MCAS EL TORO

INTERIM GROUNDWATER TREATMENT SYSTEM

MONTHLY MONITORING REPORT

AUGUST 1990

BACKGROUND

James M. Montgomery, Consulting Engineers, Inc. (JMM) is submitting its third of three additional monthly monitoring reports for the MCAS El Toro Interim Groundwater Treatment System as part of Contract No. N68711-85-C-5592, Modifications P00026 & P00027. JMM had previously submitted nine monthly reports covering the period from July 1989 to April 1990 as part of Modifications P00018 & P00019 to the aforementioned contract.

The system consists of three wells extracting groundwater from along the southwestern perimeter of the Base and pumping it to a granular activated carbon (GAC) treatment system near Building 319. The treated water is pumped into the golf course irrigation system. The interim groundwater treatment system has been in operation since June 15, 1989.

ACTIVITIES COMPLETED THIS MONTH

Analytical Data

o Five samples were collected August 27, 1990 for analyses. The samples collected included: one sample for the influent to Unit 1 at the GAC Treatment System, one sample for the effluent of Unit 1, and one sample for the effluent of Unit 2 were collected. Matrix spike and duplicate samples were also obtained for QA/QC analyses.

OPERATION DATA

- o Flow meter readings were taken at all three wells, the GAC treatment and the golf course storage tank.
- o PS-4 was not operating due to an electrical outage in the area. Apparently there are some short circuit problems that has disabled the panelboard at Building 802 which powers PS-4. The power was subsequently restored and PS-4 was put into operation the first week in September.
- o The tetrahydrafuran that was analyzed in the influent to the GAC several months ago has not been detected since. This compound is found in PVC solvent cement and it is postulated that its source is a result of repair work that was performed on the supply line from PS-1 to the GAC Treatment Facility.

MAINTENANCE DATA

o Conducted general housekeeping around all the sites.

DISCUSSION OF RESULTS

The three wells pumped an average of seven gallons per minute to the GAC treatment system from the beginning of August until the end of August. Only during the first month of operation has the design flow of 30 gallons per minute been achieved. Approximately 3 million gallons of groundwater have been treated during the fourteen months of operation.

Table 1 provides a summary of the analytical results for samples taken before start up of the GAC treatment system and results of subsequent monthly monitoring samples. Table 2 provides a summary of the groundwater extracted from the three wells and treated at the GAC treatment facility. Figure 1 is a schematic flow diagram of the overall extraction and treatment system including sample locations.

After replacement of one of the GAC units, the volatile organics detected in the outlet of Unit 1 are chloroform (1.7 ppb) and Cis 1,2 Dichloroethene (1.3 ppb). The original design criteria allows up to five micrograms per liter of a contaminant before procedures for replacing a carbon unit is implemented. No contaminants were detected in the effluent being pumped to the golf course storage tank.

ACTIVITIES PLANNED FOR NEXT MONTH

Unless a contract extention is negotiated, no activities are planned for the month of September 1990.

RECOMMENDATIONS

The following is a list of items that are needed to help improve the operation of the Interim Groundwater Treatment System:

- o The layout for the GAC units should be revised to facilitate changeouts of spent GAC units. The current layout requires both GAC units to be moved during changeout. Both units could be located in front of the gate so that only the spent unit needs to be moved during changeout. The influent piping would also be redone to coordinate with the new layout. This recommendation is being made since the Interim Groundwater Treatment System is being proposed to remain in operation for at least another year.
- o The entire system should be evaluated for improvements (e.g. overflow containment, buried double wall supply line, telemetry from extraction wells, IRWD use of 8-inch reclaim line for treated wastewater effluent to golf course, etc.) that may be required to meet longer term use than was originally intended.

TABLE

EL TORO INTERIM GROUNDWATER TREATMENT SYSTEM

SUMMARY OF ANALYTICAL RESULTS

	Sample Date, Concentration, ppb (μg/l)												
Location/Compound	Before startup	7/28/89	9/11/89	10/12/89	11/13/89	12/18/89	1/26/90	2/23/90 (a)	<u>3/27/90</u>	4/26/90	6/28/90 (b)	8/3/90 (c)	<u>8/27/90</u>
PS-1 Chloroform PCE TCE Cis 1,2 Dichloroethene	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	ND ND ND ND	NA
PS-3 Chloroform PCE TCE Cis 1,2 Dichloroethene	ND> 12 24> 83 33> 70 ND>7.4	2.6 76 65 5.8	NA	NA	NA	NA	NA	NA	NA	NA	NA	ND 46 81 ND	NA
PS-4 Chloroform PCE TCE Cis 1,2 Dichloroethene	ND> 3.1 48> 59 78> 98 10> 15	2.4 60 70 8	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA	NA
GAC Inlet Chloroform PCE TCE Cis 1,2 Dichloroethene 2-Butanone 1,1,2-Trichloroethane Xylenes	NA	3 100 99 7.9 ND ND	2.9 58 100 8.4 25 ND ND	3 69 150 9.2 ND ND ND	ND 68 150 5 ND ND ND	3.2 54 160 4.8 ND ND ND	2.7 58 130 6.1 ND 2.4 2.2	1.8 56 92 6.3 ND 1.2 ND	ND 47 97 5.6 ND ND ND	ND 49 72 7.4 ND ND ND	ND ND 9 ND ND ND ND	ND 39 75 ND ND ND ND	ND 25 95 ND ND ND ND
Unit 1 Outlet Chloroform PCE TCE Cis 1,2 Dichloroethene 1,1-Dichloroethene 1,1-Dichloroethene 1,1-Dichloroethene 1,1-Z-Trichloroethene	NA	ND 0.6 0.2 ND ND ND ND ND	0.2 ND ND ND ND ND ND ND	0.6 ND ND 1.3 ND ND ND	1.4 ND ND 1.4 0.4 ND ND	1.7 ND ND ND 0.4 1.7 ND	2.9 ND 2.1 5.8 0.6 0.2	0.8 ND ND ND ND ND ND ND	0.7 ND ND ND ND ND ND ND	1.0 ND ND ND ND ND ND	0.7 ND ND ND ND ND ND ND	1.6 ND ND 0.5 ND ND ND ND	1.7 ND ND 1.3 ND ND ND ND
GAC Outlet Chloroform PCE TCE Cis 1,2 Dichloroethene 1,1-Dichloroethane	NA	ND ND ND ND ND	ND ND ND ND	ND ND ND ND ND	ND ND ND ND	ND ND ND ND ND	0.2 ND ND ND 0.1	ND ND ND ND	ND ND ND ND	ND ND ND ND ND	ND ND ND ND	ND ND ND ND ND	ND ND ND ND
Groundwater Treated each month, gallons	NA	205,790	459,085	263,550	352,046	252,345	364,538	299,365	150,296	130,025	69,392	171,255	245,598

Legend:

NA- No analysis

ND- Not detected

(a) Unit 1 was replaced with a new unit
(b) - PS-1 was the only extraction well in operation at the time of the sample.
(c) - The power supply for PS-4 was disconnected so a sample could not be collected.

TABLE 2

EL TORO GROUNDWATER TREATMENT SYSTEM


SUMMARY OF FLOW RATES

	July 2/1/89	July 7 <u>/29/89</u>	September 9/11/89	October 10/13/89	November 11/13/89	December 12/18/89	January 1/26/90	February 3/2/90	March 3/27/90	April 4/26/90	June 6/28/90	July (a) 8/3/90	August 8/27/96	1989/1990 Total
PS-1:														
Meter reading gal	NA	300	569	8,100	8,100	8,100	8,440	16,150	17,890	39,220	58,770	58,930	72,200	
Gallons pumped		300	269	7,531	0	0	340	7.710	1,740	21,330	19,550	160	13,270	72,200
Days	0	22	44	32	31	35	39	35	25	30	63	36	24	416
Ave flow,gpm	0	0.01	0.0044	0.16	0.00	0.00	0.01	0.15	0.05	0.49	0.22	0.00	0.38	0.12
PS-3:														
Meter reading gal	6,470	22,580	235,590	368,870	550,750	731,730	924,700	1,071,920	1.071.920	1,105,810	1,105,990	1,125,010	1,356,580	
Gallons pumped	6,470	16,110	213,010	133,280	181,880	180,980	192,970	147,220	0	33.890	180	19,020	231,570	1,356,580
Days	0	22	44	32	31	35	39	35	25	30	63	36	24	416
Ave flow,gpm	35.94	0.51	3.36	2.89	4.07	3.59	3.44	2.92	0.00	0.78	0.00	0.37	6.70	2.26
PS-4:														
Meter reading gal	5,930	189,730	426,500	569,870	732,470	798,850	1,019,330	1,162,480	1,300,120	1,384,180	1,435,630	1,435,630	1,435,630	
Gallons pumped	1,860	183,800	236,770	143,370	162,600	66,380	220,480	143,150	137,640	84,060	51,450	0	0	1,435,630
Days	0	22	44	32	31	35	39	35	25	30	63	36	24	416
Ave flow,gpm	10.33	5.80	3.74	3.11	3.64	1.32	3.93	2.84	3.82	1.95	0.57	0.00	0.00	2.40
GAC:														
Meter reading, cuft	1,301	28,813	90,188	125,422	172,487	206,223	254,958	294,980	315,073	332,456	341,733	364,628	397,462	
Gallons pumped	4,555	205,790	459,085	263,550	352,046	252,345	364,538	299,365	150,296	130,025	69,392	171,255	245,598	2,973,016
Days	0.131	22	44	32	31	35	39	35	25	30	63	36	24	416
Ave flow,gpm	25.31	6.50	7.25	5.72	7.89	5.01	6.49	5.94	4.17	3.01	0.76	3.30	7.11	4.96
Golf Course Storage Tank														
Meter reading, cuft	39,903,500	41,678,000	44,641,300	45,982,500	46,757,000	47,813,700	48,438,600	49,143,200	49,777,600	50,482,000	53,562,800	56,734,800	58,338,100	
Gallons pumped		13,273,260	22,165,484	10,032,176	5,793,260	7,904,116	4,674,252	5,270,408	4,745,312	5,268,912	23,044,384	23,726,560	11,992,684	137,890,808
Days		22	44	32	31	35	39	35	25	30	63	36	24	416
Ave flow,gpm	0.00	419	350	218	130	157	83	105	132	122	254	458	347	230
Treated Groundwater as of a %		1.6%	2.1%	2.6%	6.1%	3.2%	7.8%	5.7%	3.2%	2.5%	0.3%	0.7%	2.0%	2.2%
of Golf Course Irrigation Water														

(a) Flow meters at PS-1 &PS-4 were not working

INTERIM G()UNDWATER TREATMENT SYSTEM SCHEMATIC FLOW DIAGRAM

FIGURE 1



ANALYTICAL RESULTS

a division of James M. Montgomery, Consulting Engineers, Inc. 555 East Walnut Street, Pasadena, California 91101 (818) 796-9141 / (213) 681-4255 Telex 67-5420

Report of GC/MS Analysis for VOLATILE ORGANICS in Water

Navy (MCAS-El Toro) / JMM-WCK

501 Lennon Lane

Suite 200

Walnut Creek, CA 94598

Attn: Rick Wilson

Job#:

226.0380

PO#:

Workorder#: W30654

Report#:

R46871

Phone #:

415-933-2250

Date Sampled: Date Analyzed: 8/27/90 9/4/90

Date Received:

8/27/90

Sample I.D.:

Lab Number:

K86164

GAC 1

Compound

Concentration (micrograms/liter)

Detection Limit (micrograms/liter)

VOLATILE PRIORITY POLLUTANTS:

	Acrolein	ND	25
	Acrylonitrile	ND	25
	Benzene	ND	12.5
	Bromoform	ND	12.5
	Carbon Tetrachloride	ND	12.5
	Chlorobenzene	ND	12.5
	Dibromochloromethane	ND	12.5
	Chloroethane	ND	25
	2-Chloroethylvinylether	ND	25
	Chloroform	ND	12.5
	Dichlorobromomethane	ND	12.5
	1,1-Dichloroethane	ND	12.5
~	1,2-Dichloroethane	ND	12.5
	1,1-Dichloroethene	ND	12.5
	1,2-Dichloropropane	ND	12.5
	Ethylbenzene	ND	12.5
	Methyl Bromide	ND	25
	Methyl Chloride	ND	25
	Methylene Chloride	ND	125
₩	1,1,2,2-Tetrachloroethane	ND	12.5

ND: Not Detected

NA: Not Analyzed

HSL compounds are tentative quantitations based on single point calibration.

Approved by

内とでも、シュー、。

SEP D7 銀月

QC OFFICER

Lab Number: Sample I.D.: K86164 GAC 1

Compound	Concentration (micrograms/liter)	Detection Limit (micrograms/liter)
VOLATILE PRIORITY POLLUTANTS	G (continued):	
Tetrachloroethene	25	12.5
Toluene	ND	12.5
1,1,1-Trichloroethane	ND	12.5
1,1,2-Trichloroethane	ND	12.5
Trichloroethene	95	12.5
Vinyl Chloride	ND	25
trans-1,3-Dichloropropene	ND	12.5
cis-1,3-Dichloropropene	ND	12.5
trans-1,2-Dichloroethene	ND	12.5
cis-1,2-Dichloroethene	ND	12.5
Trichlorofluoromethane	ND	25
m,p-Xylenes	ND	12.5
1,2-Dichlorobenzene	ND	12.5
1,3-Dichlorobenzene	ND	12.5
1,4-Dichlorobenzene	ND	12.5
HAZARDOUS SUBSTANCES COMPOUN	NDS:	
Acetone	ND	250
2-Butanone	ND	25
Carbon disulfide	ND	12.5
2-Hexanone	ND	25
4-Methyl-2-Pentanone	ND	25
Styrene	ND	12.5
Tetrahydrofuran	ND	250
Vinyl Acetate	ND	125
o-Xylene	ND	12.5

ND: Not Detected
NA: Not Analyzed
HSL compounds are tentative quantitations based on single point calibration.

Lab Number:	K86164		
Sample I.D.:	GAC 1		
Compound	Recovery	QC Limits	
SURROGATE:			
4-Bromofluorobenzene	106	86-115	
1,2-Dichloroethane-d4	99	76-114	
Toluene-d8	96	88-110	

ND: Not Detected

NA: Not Analyzed HSL compounds are tentative quantitations based on single point calibration.

a division of James M. Montgomery, Consulting Engineers, Inc. 555 East Walnut Street, Pasadena, California 91101 (818) 796-9141 / (213) 681-4255 Telex 67-5420

Report of GC/MS Analysis for VOLATILE ORGANICS in Water

Navy (MCAS-El Toro) / JMM-WCK

501 Lennon Lane

Suite 200

Walnut Creek, CA 94598

Attn: Rick Wilson

Date Sampled: Date Analyzed: 9/5/90

8/27/90

Job#:

226.0380

8/27/90

PO#:

Workorder#: W30654 Report#: R46872

Phone #:

Date Received:

415-933-2250

Lab Number: Sample I.D.:

K86165 GAC 1 DUP

Compound	Concentration (micrograms/liter)	Detection Limit (micrograms/liter)
VOLATILE PRIORITY POLLUTANTS:		
crolein	ND	25
Acrylonitrile	ND	25
Benzene	ND	12.5
Bromoform	ND	12.5
Carbon Tetrachloride	ND	12.5
Chlorobenzene	ND	12.5
Dibromochloromethane	ND	12.5
Chloroethane	ND	25
2-Chloroethylvinylether	ND	25
Chloroform	ND	12.5
Dichlorobromomethane	ND	12.5
1,1-Dichloroethane	ND	12.5
1,2-Dichloroethane	ND	12.5
1,1-Dichloroethene	ND	12.5
1,2-Dichloropropane	ND	12.5
Ethylbenzene	ND	12.5
Methyl Bromide	ND	25
Methyl Chloride	ND	25
Methylene Chloride	ND	125
1,1,2,2-Tetrachloroethane	ND	12.5

ND: Not Detected

NA: Not Analyzed

HSL compounds are tentative quantitations based on single point calibration.

Approved by

APPEN A

SEP 1 5 1997

QC OFFICER

Lab Number:

K86165

Sample I.D.:	GAC 1 DUP			
Compound	Concentration (micrograms/liter)	Detection Limit (micrograms/liter)		
VOLATILE PRIORITY POLLUTANT	S (continued):			
Tetrachloroethene	50	12.5		
Toluene	ND	12.5		
1,1,1-Trichloroethane	ND	12.5		
1,1,2-Trichloroethane	ND	12.5		
Trichloroethene	140	12.5		
Vinyl Chloride	ND	25		
trans-1,3-Dichloropropene	ND	12.5		
cis-1,3-Dichloropropene	ND	12.5		
trans-1,2-Dichloroethene	ND	12.5		
cis-1,2-Dichloroethene	ND	12.5		
Trichlorofluoromethane	ND	25		
m,p-Xylenes	ND	12.5		
1,2-Dichlorobenzene	ND	12.5		
1,3-Dichlorobenzene	ND	12.5		
1,4-Dichlorobenzene	ND	12.5		
"IAZARDOUS SUBSTANCES COMPOU	NDS:			
Acetone	ND	250		
2-Butanone	ND	25		
Carbon disulfide	ND	12.5		
2-Hexanone	ND	25		
4-Methyl-2-Pentanone	ND	25		
Styrene	ND.	12.5		
Tetrahydrofuran	ND	250		
Vinyl Acetate	ND	125		
o-Xylene	ND	12.5		

Not Detected ND:

NA: Not Analyzed HSL compounds are tentative quantitations based on single point calibration.

Lab Number: Sample I.D.:

K86165 GAC 1 DITP

Sample 1.D.:	GAC I DUP		
Compound	Recovery (%)	QC Limits	
SURROGATE:			
4-Bromofluorobenzene 1,2-Dichloroethane-d4 Toluene-d8	113 98 110	86-115 76-114 88-110	

Not Detected ND:

NA: Not Analyzed

HSL compounds are tentative quantitations based on single point calibration.

a division of James M. Montgomery, Consulting Engineers, Inc. 555 East Walnut Street, Pasadena, California 91101 (818) 796-9141 / (213) 681-4255 Telex 67-5420

Report of GC/MS Analysis for VOLATILE ORGANICS in Water

Navy (MCAS-El Toro) / JMM-WCK

501 Lennon Lane

Suite 200

Walnut Creek, CA 94598

Attn: Rick Wilson

Job#:

226.0380

PO#:

Workorder#: W30654

R46873

Report#:

Phone #:

415-933-2250

Detection Limit

0.50

Date Sampled: Date Analyzed: 8/27/90 9/5/90

Date Received:

8/27/90

Sample I.D.:

Lab Number:

K86166

GAC 2

Compound	(micrograms/liter)	(micrograms/liter)
VOLATILE PRIORITY POLLUTANTS	5:	
Acrolein	ND	1.0
crylonitrile	ND	1.0
Benzene	ND	0.50
Bromoform	ND	0.50
Carbon Tetrachloride	ND	0.50
Chlorobenzene	ND	0.50
Dibromochloromethane	ND	0.50
Chloroethane	ND	1.0
2-Chloroethylvinylether	ND	1.0
Chloroform	1.7	0.50
Dichlorobromomethane	ND	0.50
1,1-Dichloroethane	ND	0.50
1,2-Dichloroethane	ND	0.50
1,1-Dichloroethene	ND	0.50
1,2-Dichloropropane	ND	0.50
Ethylbenzene	ND	0.50
Methyl Bromide	ND	1.0
Methyl Chloride	ND	1.0
Methylene Chloride	ND	5.0

Concentration

ND: Not Detected

1,1,2,2-Tetrachloroethane

NA: Not Analyzed

HSL compounds are tentative quantitations based on single point calibration.

ND

Approved by

APPENDE

SEP 1 0 1907

OC OFFICER

Lab Number: Sample I.D.:	K86166 GAC 2			
Compound	Concentration (micrograms/liter)	Detection Limit (micrograms/liter)		
VOLATILE PRIORITY POLLUTANTS	S (continued):			
Tetrachloroethene	ND	0.50		
Toluene	ND	0.50		
1,1,1-Trichloroethane	ND	0.50		
1,1,2-Trichloroethane	ND	0.50		
Trichloroethene	ND	0.50		
Vinyl Chloride	ND	1.0		
trans-1,3-Dichloropropene	ND	0.50		
cis-1,3-Dichloropropene	ND	0.50		
trans-1,2-Dichloroethene	ND	0.50		
cis-1,2-Dichloroethene	1.3	0.50		
Trichlorofluoromethane	ND	1.0		
m,p-Xylenes	ND	0.50		
1,2-Dichlorobenzene	ND	0.50		
1,3-Dichlorobenzene	ND ND	0.50 0.50		
1,4-Dichlorobenzene AZARDOUS SUBSTANCES COMPOUN		. 0.50		
Acetone	ND	10		
2-Butanone	ND	1.0		
Carbon disulfide	ND	0.50		
2-Hexanone	ND	1.0		
4-Methyl-2-Pentanone	ND	1.0		
Styrene	ND	0.50		
Tetrahydrofuran	ND	10		
Vinyl Acetate	ND	5.0		
o-Xylene	ND	0.50		

ND: Not Detected

NA: Not Analyzed HSL compounds are tentative quantitations based on single point calibration.

Lab Number:	K86166			
Sample I.D.:	GAC 2			
Compound	Recovery (%)	QC Limits		
SURROGATE:				
4-Bromofluorobenzene	101	86-115		
1,2-Dichloroethane-d4	99	76-114		
Toluene-d8	91	88-110		

ND: Not Detected
NA: Not Analyzed
HSL compounds are tentative quantitations based on single point calibration.

a division of James M. Montgomery, Consulting Engineers, Inc. 555 East Walnut Street, Pasadena, California 91101 (818) 796-9141 / (213) 681-4255 Telex 67-5420

Report of GC/MS Analysis for VOLATILE ORGANICS in Water

Navy (MCAS-El Toro) / JMM-WCK

501 Lennon Lane

Suite 200

Walnut Creek, CA 94598

Attn: Rick Wilson

Job#:

226.0380

PO#:

Workorder#:

W30654

Report#:

R46874

Phone #:

415-933-2250

Date Sampled: Date Analyzed: 8/27/90

Date Received:

8/27/90

9/5/90

Lab Number: Sample I.D.: K86167 GAC 3

Compound	Concentration (micrograms/liter)	Detection Limit (micrograms/liter)
VOLATILE PRIORITY POLLUTANTS:		

Acrolein	ND	1.0
crylonitrile	ND	1.0
Benzene	ND	0.50
Bromoform	ND	0.50
Carbon Tetrachloride	ND	0.50
Chlorobenzene	ND	0.50
Dibromochloromethane	ND	0.50
Chloroethane	ND	1.0
2-Chloroethylvinylether	ND	1.0
Chloroform	ND	0.50
Dichlorobromomethane	ND	0.50
1,1-Dichloroethane	ND	0.50
1,2-Dichloroethane	ND	0.50
1,1-Dichloroethene	ND	0.50
1,2-Dichloropropane	ND	0.50
Ethylbenzene	ND	0.50
Methyl Bromide	ND	1.0
Methyl Chloride	ND	1.0
Methylene Chloride	ND	5.0
1,1,2,2-Tetrachloroethane	ND	0.50

ND: Not Detected

Not Analyzed NA:

HSL compounds are tentative quantitations based on single point calibration.

Approved by

SEP1 S TEST

QC OFFICER

Lab Number: Sample I.D.:	K86167 GAC 3	
Compound	Concentration (micrograms/liter)	Detection Limit (micrograms/liter
VOLATILE PRIORITY POLLUTANTS	G (continued):	
Tetrachloroethene	ND	0.50
Toluene	ND	0.50
1,1,1-Trichloroethane	ND	0.50
1,1,2-Trichloroethane	ND	0.50
Trichloroethene	ND	0.50
Vinyl Chloride	ND	1.0
trans-1,3-Dichloropropene	ND	0.50
cis-1,3-Dichloropropene	ND	0.50
trans-1,2-Dichloroethene	ND	0.50
cis-1,2-Dichloroethene Trichlorofluoromethane	ND ND	0.50
	ND ND	1.0 0.50
m,p-Xylenes 1,2-Dichlorobenzene	ND ND	0.50
1,3-Dichlorobenzene	ND ND	0.50
1,4-Dichlorobenzene	ND ND	0.50
HAZARDOUS SUBSTANCES COMPOUN		0.30
Acetone	ND	10
2-Butanone	ND	1.0
Carbon disulfide	ND	0.50
2-Hexanone	ND	1.0
4-Methyl-2-Pentanone	ND	1.0
Styrene	ND	0.50
Tetrahydrofuran	ND	10
Vinyl Acetate	ND	5.0
o-Xylene	ND	0.50

ND: Not Detected

NA: Not Analyzed HSL compounds are tentative quantitations based on single point calibration.

Lab Number:	K86167		
Sample I.D.:	GAC 3		
Compound	Recovery	QC Limits	
SURROGATE:			
4-Bromofluorobenzene	101	86-115	
1,2-Dichloroethane-d4	97	76-114	
Toluene-d8	95	88-110	

ND: Not Detected NA: Not Analyzed HSL compounds are tentative quantitations based on single point calibration.

a division of James M. Montgomery, Consulting Engineers, Inc. 555 East Walnut Street, Pasadena, California 91101 (818) 796-9141 / (213) 681-4255 Telex 67-5420

Report of GC/MS Analysis for VOLATILE ORGANICS in Water

Navy (MCAS-El Toro) / JMM-WCK

501 Lennon Lane

Suite 200

Walnut Creek, CA 94598

Attn: Rick Wilson

Job#:

226.0380

PO#:

Workorder#: W30654 R46875

Report#:

Phone #:

415-933-2250

Date Sampled: Date Analyzed: 8/27/90 9/5/90

Date Received:

8/27/90

Lab Number: Sample I.D.: K86168

GAC 3 SPIKE

Compound

% Recovery

VOLATILE PRIORITY POLLUTANTS:

Benzene	72
Chlorobenzene	75
_Chloroform	82
1,1-Dichloroethene	75
Toluene	80
Trichloroethene	92

Approved by

APPENS dien

QC OFFICER

Lab Number: Sample I.D.: Compound	K86168 GAC 3 SPIKE		
	Recovery	QC Limits	
SURROGATE:			
4-Bromofluorobenzene	97	86-115	
1,2-Dichloroethane-d4	96	76 - 114	
Toluene-d8	93	88-110	

a division of James M. Montgomery, Consulting Engineers, Inc. 555 East Walnut Street, Pasadena, California 91101 (818) 796-9141 / (213) 681-4255 Telex 67-5420

Report of GC/MS Analysis for VOLATILE ORGANICS in Water

Navy (MCAS-El Toro) / JMM-WCK

501 Lennon Lane

Suite 200

Walnut Creek, CA 94598

Attn: Rick Wilson

Job#:

226.0380

PO#:

Workorder#: Report#:

W30654 R46876

Phone #:

415-933-2250

Date Sampled: Date Analyzed: 8/27/90 9/4/90

Date Received:

8/27/90

Lab Number: Sample I.D.:

K86169

TRAVEL BLANK 8/20/90

Compound	Concentration (micrograms/liter)	Detection Limit (micrograms/liter)
VOLATILE PRIORITY POLLUTANTS	6:	
Acrolein	ND	1.0
Acrylonitrile	ND	1.0
Benzene	ND	0.50
Bromoform	ND	0.50
Carbon Tetrachloride	ND	0.50
Chlorobenzene	ND	0.50
Dibromochloromethane	ND	0.50
Chloroethane	ND	1.0
2-Chloroethylvinylether	ND	1.0
Chloroform	ND	0.50
Dichlorobromomethane	ND	0.50
1,1-Dichloroethane	ND	0.50
1,2-Dichloroethane	ND	0.50
1,1-Dichloroethene	ND	0.50
1,2-Dichloropropane	ND	0.50
Ethylbenzene	ND	0.50
Methyl Bromide	ND	1.0
Methyl Chloride	ND	1.0
Methylene Chloride	ND	5.0
1,1,2,2-Tetrachloroethane	ND	0.50

ND: Not Detected Not Analyzed NA:

HSL compounds are tentative quantitations based on single point calibration.

Approved by

Lab Number: Sample I.D.:

K86169 TRAVEL BLANK 8/20/90

Compound	Concentration (micrograms/liter)	Detection Limit (micrograms/liter)
VOLATILE PRIORITY POLLUTANTS	G (continued):	
Tetrachloroethene	ND	0.50
Toluene	ND	0.50
1,1,1-Trichloroethane	ND	0.50
1,1,2-Trichloroethane	ND	0.50
Trichloroethene	ND	0.50
Vinyl Chloride	ND	1.0
trans-1,3-Dichloropropene	ND	0.50
cis-1,3-Dichloropropene	ND	0.50
trans-1,2-Dichloroethene	ND	0.50
cis-1,2-Dichloroethene	ND	0.50
Trichlorofluoromethane	ND	1.0
m,p-Xylenes	ND	0.50
1,2-Dichlorobenzene	ND	0.50
1,3-Dichlorobenzene	ND	0.50
1,4-Dichlorobenzene	ND	0.50
HAZARDOUS SUBSTANCES COMPOUN	IDS:	
Acetone	ND	10
2-Butanone	ND	1.0
Carbon disulfide	ND	0.50
2-Hexanone	ND	1.0
4-Methyl-2-Pentanone	ND	1.0
Styrene	ND	0.50
Tetrahydrofuran	ND	10
Vinyl Acetate	ND	5.0
o-Xylene	ND	0.50

ND: Not Detected

NA: Not Analyzed HSL compounds are tentative quantitations based on single point calibration.

76-114

88-110

Report of GC/MS Analysis for VOLATILE ORGANICS in Water

Lab Number:
Sample I.D.:

Recovery
(%)

Compound

Recovery
(%)

SURROGATE:

4-Bromofluorobenzene

K86169

TRAVEL BLANK 8/20/90

Recovery
(%)
(%)

86-115

95

97

ND: Not Detected

NA: Not Analyzed

1,2-Dichloroethane-d4

Toluene-d8

HSL compounds are tentative quantitations based on single point calibration.

DESTINATION: MONTGOMERY LABORATORIES Montgomery JON TOBYEL BY AND WELL BY AND CHAIN OF CUSTODY RECORD OTHER: Consulting Engineers Inc. Analyses Required PROJECT/JOB # PROJECT NAME MCAS - EL TORO 226.0380 SAMPLER(S): (Signature) Sample Location Number/Size Grab Comp. of Containers I.D. 8/27/90 8=15 am 3 4AC k86166 3 KB6167 3 **K8**6168 8:30am BAC 3 k86169 T-BLANK Company/Title Date Time Signature Print Name JMM 8/27/90 8-30ab Relinguished by: 4. SPEED Recieved by: Relinquished by: Recieved by: Relinquished by: JM Montgomeny 8/27/90 2:10 Recieved by (Lab): Gricelda acens Griceldo Acenes WCK: 5/89 Page

1